RESOLUTION NO. 6486-2022

RESOLUTION OF THE CITY COUNCIL OF THE CITY OF SEBASTOPOL APPROVING AN OUT OF SERVICE AREA AGREEMENT (OSAA) FOR CONNECTION TO THE CITY SEWER SYSTEM AND AUTHORIZING THE CITY MANAGER TO EXECUTE THE OSAA FOR THE LANDS OF BRYAN M. DOHERTY, JR. AND MARILYN ZICK, TRUSTEES FOR THE ZICK/DOHERTY FAMILY TRUST U/D/T MARCH 17, 2000, 286 EDDIE LANE, SEBASTOPOL, CALIFORNIA 95472 (APN 060-290-008)

WHEREAS, Bryan M. Doherty, Jr. and Marilyn Zick, Trustees for The Zick/Doherty Family Trust U/D/T March 17, 2000 ("OWNERS") are the owners of record of Assessor's Parcel Number 060-290-008 ("Property"), located at 286 Eddie Lane, Sebastopol, California, 95472; and

WHEREAS, Property is located outside the City of Sebastopol's jurisdictional boundaries and the City's Sphere of Influence; and

WHEREAS, OWNERS submitted to the City a request for allowing Property to connect to the City's sanitary sewer system in Eddie Lane; and

WHEREAS, OWNERS' request includes an application for Out of Service Area Agreement (OSAA), documentation on Property legal status of existing legal non-conforming 3-bedroom single family rural residence within a Diverse Agricultural Zoning District, and documentation of an existing or impending threat to public health and safety due to the non-conforming failing septic system that includes a septic tank in poor condition thus necessitating the request for connection; and

WHEREAS, pursuant to Municipal Code Section 13.08.200, paragraph F the City of Sebastopol may provide sanitary sewer service outside its jurisdictional boundaries pursuant to City Council approving an out of service area agreement subject to approval of the Sonoma County Local Agency Formation Commission (LAFCO), and under terms and conditions adopted and amended from time to time by the City, when an existing on-site sewage disposal system due to its failing substandard condition as determined by the Sonoma County Permit and Resource Management Department (PRMD) is a threat to the health and safety of the public or the affected residents; and

WHEREAS, the PRMD reviewed the documentation submitted by OWNERS and has determined that: the existing septic system meets the definition of a non-conforming septic system; the septic tank is in poor condition; and the septic system is failing; and

WHEREAS, the City of Sebastopol sanitary sewer system is located in Eddie Lane adjacent to the Property, is available for the connection requested, and the system capacity is adequate.

NOW, THEREFORE BE IT RESOLVED, that the City Council of the City of Sebastopol, as follows:

- 1. Finds the foregoing recitals are true and correct.
- 2. Approves an Out of Service Area Agreement (OSAA) for sewer connection for property located at 286 Eddie Lane, Sebastopol, California, 95472, APN 060-290-008, subject to LAFCO approval and under terms and conditions adopted and amended from time to time by the City.

3. Authorizes the City Manager to execute the OSAA.

The above and foregoing Resolution was duly passed, approved, and adopted at a meeting by the City Council on the 1st day of November 2022.

I, the undersigned, hereby certify that the foregoing Resolution was duly adopted by City of Sebastopol City Council following a roll call vote:

VOTE: Ayes:

Noes:

Councilmembers Glass, Gurney, Rich, Vice Mayor Hinton and Mayor Slayter None

Absent: None Abstain:

None

APPROVED: Mayor Patrick Slayter

y C. Gourley Mary Gourley, Assistant City Manager/City Clerk, MMC ATTEST

APPROVED AS TO FORM:

ale

Larry McLaughlin, City Attorney



CITY OF SEBASTOPOL

 Engineering Division 714 Johnson Street Sebastopol, CA 95472 (707) 823-2151 Phone (707) 823-4721 Fax

APPLICATION FORM FOR OUTSIDE SERVICE AREA AGREEMENT

(Outside of City Sewer and Water Services)

Property Address: <u>286 Eddie Ln</u> Assessor's Parcel No: <u>060-290-008</u>

Type of Service Requested: 🛛 Sewer Only

□ Water Only

Applicant (if other than Owner)

□ Sewer and Water

Owner of Record

Name:	Brian Doherty_	Name:	hate Doherty
Mail Address:	496 W Avenida de las Flores	Mail Address:	286 Eddie Ln
City State 7im	Thousand Oaks, CA 91360	City, State, Zip:	Sebastopol, CA 95472
Phone:	(805) 402-3914	Phone:	(805) 2-31-1088
Fax:		Fax:	
e-mail:	bmdohertyjr e maccom	e-mail:	Kabdoberty equail.com
	Bin John Signature		Signatore
Date:	7/21/21	Date:	7/21/21
Parcel Informatio	'n		

1. Parcel Size (Acres):	1.79	Existing Land Use:	Rural	Residential;	Zoned	DA
-------------------------	------	--------------------	-------	--------------	-------	----

2. Describe existing development on the parcel. (Outside of City services are for existing development only.)

A 3-bedroom house and 2 large borns.

Status of Existing Development (Check One):□Legal☑Legal Non-Conforming☑Documentation of Legal Status of Existing Development is attached (required).NOTE:You must provide documentation from the Sonoma County Permit and Resource Management Department (PRMD) regarding
the status of existing development. (See Attachment entitled "City of Sebastopol, Outside of Service Area Agreements")

3. Reason for Requesting City Services:

Failed septic system, no viable space for an alternative septic, city sewer located at property line.

Documentation of existing or potential threat to public health and safety is attached (required). NOTE: You must provide documentation from PRMD Well and Septic Division of an existing or potential threat to public health or safety as a part of your complete application. (See Attachment entitled "City of Sebastopol, Outside of Service Area Agreements")

4. Additional Information: (Please attach additional sheets as necessary.)

For Office	Use Only
Deposit Received: \$ 2,500.00	Receipt No: 160168
	Date: 7-25-2022
□Application Complete	Engineering File No: 22-01



Kate Doherty <kdbdoherty@gmail.com>

286 Eddie Lane_APN 060-290-008

1 message

Brian Keefer <Brian.Keefer@sonoma-county.org> To: "kdbdoherty@gmail.com" <kdbdoherty@gmail.com> Thu, Jul 21, 2022 at 8:33 AM

Hello Kate,

The Assessor's field notes for this property establish that the existing 3-bedroom house was constructed far prior to 1963 when the County started administering building permits. This means your house is a legal non-conforming 3-bedroom single family residence. The historic and legal use of the property is rural residential within a Diverse Agricultural (DA) Zoning District.

Please let me know if you need any further assistance.

Brian Keefer

Ombudsman

www.PermitSonoma.org

County of Sonoma

Administration Division | Customer Service

2550 Ventura Avenue, Santa Rosa, CA 95403

Direct: 707-565-8350 | Office: 707-565-1900



Parcel Report

County Assessor Information

7/26/2022 1:57:52 PM

Situs Address:	286 EDDIE LN		
Situs CSZ:	SEBASTOPOL, CA 95472		
Owner:	Doherty Bryan M Jr Tr & Z		
In Care Of:			
Address:	496 W AVENIDA DE LAS FLORI		
CSZ:	THOUSAND OAKS CA 91360		
Land Use:	RURAL RES/SINGLE RES		
Tax Area:	155008		
Jurisdiction:	COUNTY		
Recording#:	2020R047559		1
Rec Date:	6/16/2020		
	4074 000	Commercial Units:	
Land Value:	\$371,003	Residential Units:	1
Improvements:	\$257,641	Bedrooms:	3
Owner Exempt:	\$0	Bathrooms:	1
Subdivision:		Main Bldg SqFt:	963
		Year Built:	1926

Lot Acres: 1.79

GIS Calculated Information

Local Information

Zoning Code:

General Plan Code:

Lot Acres:	1.93
Census Tract:	153406
Census Block:	1000
Latitude:	38.4090
Longitude:	-122.8250

This report is a user generated static output from an Internet mapping site and is for reference only. Data that appear on this report may or may not be accurate, current, or otherwise reliable. GIS Calculated Lot Acres is NOT official. Assessessor Data is maintained by Sonoma County.

Request for Well and Septic Service WLS-006

*	
PURPOSE: This form is used to request a paid service f Resource Management Department (PRMD) related to a	rom the Well & Septic Division of the Permit and
application may be required following the requested	service.
June 19, 2022 Date of Request	WSR22-0633
	SEV Number
286 Eddie Lane	High School Road
Site Address	Cross Street
Sebastopol, CA 95472	060-290-008
City/Town Zip	Assessor's Parcel Number
Tai Nguyen	Bryan Doherty
Applicant Name	Property Owner's Name
P.O. Box 11247 Santa Rosa, CA 95406	286 Eddie Lane in Sebastopol, CA 95472
Mailing Address State/Zip	Mailing Address State/Zip
(707) 322-5827	(805) 402-3914
Day Phone	Day Phone
Service Requested:	
ocivice Requested.	
Review of consultant residential finding repo	ort, tier 2 (failing sentic system)
9 1	
() DO NOT WRITE BELOW THIS LIN	E - To Be Completed by PRMD Staff 🕘
Code Enforcement Violation Yes No No	Violation #
Status	
Staff Comme	nts/Notations
The Findings Report has been reviewed. The system	n meets the definition of a non-conforming sentic
system. The septic tank is in poor condition and the	e sentic system is failing
eyeterin the separe tank is in poor condition and the	septic system is failing.
Consultantle Finding Denotes to the hold of the	
Consultant's Findings Report stated that public sew	er is available within 200 feet from the property.
Per OWTS Manual Section 2, installation of a new o	r replacement dispersal system OWTS where
public sewer is available is prohibited.	

Chris Luu

Digitally signed by Chris Luu DN: cn=Chris Luu, o=Permit Sonoma, ou, email=chris.luu@sonoma-county.org, c=US Date: 2022.07.01 10:23:23 -07'00'

Staff Signature

7/1/2022 Date Completed

Sonoma County Permit and Resource Management Department

2550 Ventura Avenue Santa Rosa, CA S 95403-2829 (707) 565-1900 Fax (707) 565-1399

sue waxman S:\Handouts\WLS\WLS-006 Request for Well and Septic Service.wpd

03/09/06

Apex Septic Design, Inc.

Principal Consultant Tai Nguyen, REHS #7177

P.O. Box 11247(707) 322-5827Santa Rosa, CA 95406apexsepticdesign@gmail.com



June 18, 2022

Kate Doherty kdbdoherty@gmail.com

Re: Report of septic system findings, tier 2 at 286 Eddie Lane in Sebastopol, CA 95472 Assessor Parcel Number: 060-290-008

I conducted a septic system evaluation on June 17, 2022 at 11:30 a.m. I found the following:

Permit History

1. I completed a septic record research at the Sonoma County Permit and Resource Management Department. There is a well permit approved in 1986. In 2020, a pre-perc was conducted to determine the soil characteristic to install a new septic system.

Site Observation

2. The septic tank and leach lines are more than 50 feet away from the site water well. The downspouts of the house's roof drainage are diverted away from the leach field. The house has been occupied by 1 person. There is a drainage ditch as noted on the attached site plan. The property owner described the soil on the subject parcel to be saturated, ponded water with storm drainage in the winter; this is evidence by photos taken by the owner, see pages 8-10.

Septic Tank

3. The septic tank is located at the east side of the house, 36 feet away from the house and buried under 9 to 12 inches to soil cover. The septic tank wasn't pumped during my inspecting since it had been pumped by Felix from Vineyard Septic Service on September 4, 2019. There was .5 inches of scum and 4 inches of sludge in the inlet compartment and zero scum and sludge in the outlet compartment. The wastewater level was 1 inches above the invert of the outlet pipe. The plastic inlet and outlet baffles were intact and in working condition. I didn't see any crack or root intrusion in the septic tank. There was a break/hole on top of the septic tank next to the outlet manhole, see picture on page 4. Because of the break/hole in the septic tank, it is on poor condition.

Leach Field

4. The leach line was located and marked by Vineyard Septic Service on September 5, 2019. There is one leach line which is 38 feet long. Green lust vegetation was seen at two areas near the leach line. I conducted a hydraulic load test by adding approximately 150 gallons of water with green liquid dye to the septic tank's outlet compartment which would run into the leach field.

After filling 60 gallons of water to the leach line, I saw sewage surfacing onto the ground above the distribution box, see pages 6 and 7. Thus, the leach line failed the hydraulic load test.

Reserve Area

5. There is not an available septic reserve area on the parcel due to high groundwater.

Septic System Evaluation

6. The septic tank is in poor condition because of the hole at the top of the septic tank which can allow groundwater and soil to enter. The leach line is failing.

I would recommend that the parcel be connected to city sewer rather than installing a new septic system for the following reasons:

A) The parcel has high groundwater and has drainage swale in the winter.

B) Repairing existing 38 feet of existing leach line and adding new leach line of 19 feet (maximum length allowed by the county under repair permit) will not be enough to support wastewater from the 3-bedroom house.

C) Installing a mound system is not feasible due to the cost of approximately \$75,000 to \$100,000 which includes addition soil testing, survey, county permits, soil lab samples, design and installation with inflation of materials and is also not recommended due to flooding of the space available for a mound system.

D) City sewer is near to the parcel and house. City sewer is on the Eddie Lane next to the parcel and approximately 75 feet away from the house.

This report describes the conditions of the septic system during the time of visit. Apex Septic Design, Inc. has not been retained to warrant, guarantee, or certify the proper functioning of the septic system for any period of time in the future. Because of the numerous factors (usage, soil characteristics, previous failures, etc.) which may effect the proper operation of the septic system, this report shall not be construed as a warranty by our company that the system will function properly for any particular buyer. Apex Septic Design, Inc. DISCLAIMS ANY WARRANTY, either expressed or implied, arising from the inspection of the septic system or this report. We are also not ascertaining the impact the septic system is having on the groundwater. Apex Septic Design, Inc. is not liable for the information or lack of information shown for the record documents attached to this report.

For further information or questions I can be reached at (707) 322-5827.

Respectfully,

Ta Aguy

Tai Nguyen Registered Environmental Health Specialist #7177



Location of the Septic Tank



Hole/opening at outlet compartment of the Septic Tank



Liquid dye was added to the wastewater in the septic tank's outlet compartment



Page - 5 - of 12 Page 12 of 23 Wastewater was seen surfacing onto the ground above the distribution box



Close up picture of wastewater was seen surfacing onto the ground



Pictures of ponded water in the winter







Septic Tank Pumping Receipt

	Mitty	VINEYA	RD SEPTIC S	ERVICE
			nk Pumping • 24 7600 Beth Cou	irt de la companya de
X .		F P	ohnert Park, CA	94928
	and the second second	(707)	795-5780 (707) Fax: (707) 795-1	883
	No. 9517		Date: 9-4-	
		RY E.I		,
		Eddie		
25 ARRO 1 5				29
AL AL	\cap	STOPOL S	0 11129	
PI	hone	-07-52	281428	
Cash	C	.O.D.	Charge	On account
				AMOUNT
576	mp Septic Tank P	UMP 800	CALIDIAS	AMOUNT
	bor Septic	01019 000	GALLONS	#385.00
	nk Locator			HP-C-C-
- Pui	np Grease	1 HOUXL	ARAR	
DA	ditional Charges	FAV D.C	aing	
- Mat	terial UR 1	ids	101-1	\$\$75.00
	<u> </u>	1000		pp 1
	The second	Jack Street		
	TTAI -			D# 460.00
	UAL			the second
Y				
		Dat 1 11 1	210 %	20, 0
Paid on	account	\square Cash	2127	$-\partial D$
NOTICE: U	nder the Mechanics' Lie		e of Civil Procedure) any c	ontractor, subcontractor, laborer,
supplier, or ot	her person who helps	to improve your prope	erty but is not paid for his v	work or supplies has a right to enforce
a claim agains the proceeds	t your property. This m of sale used to satisfy y	eans that after a court our endebtedness. Thi	nearing, your property co s can happen even if you h	uld be sold by a court officer and ave paid your own contractor in
		upplier remains unpaid		

This company will not be held responsible for damage or breakage on property. The owner assumes all responsibility.

Signature

Receipt of leach line located

0 7600 B Rohnert P (707) 795-5780	ng • 24 Hour Service
• No. 9519 Date: 7	7-5-19
Name MARY E, ENGEN	
Address 286 Eddle LI	V
City SebaStoPOL CA	
Phone	
Cash C.O.D. Charge	On account
DESCRIPTION	AMOUNT
Pump Septic Tank TNSTALLed	
Tank Locator	\$285.00
Pump Grease OCATED 2Dist	WBITION BOX
Additional Charges AND 1 PRACH	IN1 \$ 75.00
And Notes D. Box 15 0	Id A
They Pres ACMANCE	thá là
10001 Ling Be ANOther	
But my in the mid	die houring
TOTAL TOTAL OF ONLY 90.	esto Ling Him.
Paid on account Check # 1212	-77 D 360:00
Cash 1213	and the second sec
NOTICE: Under the Mechanics' Lien Law (California Code of Civil Procedure) supplier, or other person who helps to improve your property but is not paid for	tis work or supplies has a right to only
the proceeds of sale used to satisfy your endebtedness. This can bappen own fit	by sould be sold by a court officer and
ion, if the subcontractor, laborer, or supplier remains unpaid.	
This company will not be held responsible for damage or breakage on The owner assumes all responsibility.	property.

3313 Chanate	OMA PUBLIC HEALTH DE Road • (707) 527-2711	PT.			- Constant of	
Santa R	osa, California 95404	Application			Receipt Informa	tion
WELLADORESS 286 Ed		WATER	Application I	83-86		1000: 137
MOPERTY OWNER Alvin		AP. NO #0	60-290-08			
	lie Ln. Seb.	PHONE NO	823-5887			0KN 13
DRILLING CONTRACTOR FIS	ch Bros. Drillin	E CONTRACTOR	#100226			DAN 137.
ADDRESS SUDI Gray	enstein Hwy. N S	eb. PHONE NO	823-3891		\$ 109.185 1	4:52 62
	Reconstruct Test we Coservation Test hol	le Class II Permit	Wet C	Reconstruct	Test well. D Test hole Destruct E]
USE Single Fam		rrigation 🗋	Industrial 🗋	Recharge	Test D Other	
CONSTRUCTION PROPOSED Casing: Diameter:5	Gauge: c160 Material:	pvc Conductor	yes D Sing no D Doub	le D Par	al yes £ Type of to no 1 Joint 1aj	2
Method of	Depth Of Seat Concrete:			Cizy		
Disinfection: chorlna	tion	;	lethod of Sealing ccess Opening: We	11 seal		
Well located within an existing put	bāc water system boundary: 🛛 Yes					
Site approved by	FOR OFFICEUSE ONLY	- ENVIR	ONMENTAL HE	ALTH SERVICE	3105. 41×1	7
Construction approval by	TC 2 the			PLA Ser	res Scarce Area I yes V.	R.
Indicate below the exact location o and laterals and private sewage of accuracy of the information provide	I well with respect to the following iten Asposal systems or other sources of ad by the applicant.	ns: property lines, w contamination or p	the second s		C I I I I I I I I I I I I I I I I I I I	e nain Krista
AUTY KED		6	EILD		Plasa	
Perfect in	QE6 EDDIE LN.		Ì ⁰ ,	×	NPR 1: 1995	
				50 +	erry server	LINE
Dut en					EDDIE LU	
7HS EH 1/1 8-83	Distribution White . S	and a single fragment				2

•

fstribution; White - Sanitarian / Canary - Well Drifter / Pink - EH file





SEPTIC SYSTEM EVALUATION SEBASTOPOL, CA 95472 APN: 060-290-008







Request for Out of Service Area Agreement for Sewer Connection at 286 Eddie Lane